Inspection Report

Name of Work	: Construction of Culverts and Repairs, Reconstructions of Secondary Nala in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.
Work Order	: EE/BTP/BBMP/E-PMT-07(13873)/WO/184/2014-15 Dated: 07.01.2015.
Agency	: Mohan Kumar. V
B.R. No & Date	: 476/2014-15 Dated: 28.02.2015
Bill Amount	: 14,83,958.00
Job Code	: 011-15-000008
P. Code	: P-1771
Date of Inspection	: 16-02-2016.

The above said work Construction of culverts and Repairs, Reconstructions of Secondary nala in ward no 11 (Kuvempunagara) Vidyaranyapura Sub Div. was shown to me by the Concerned A.E, Shri Ranganath.

The above said work was inspected by me along with the Concerned A.E.

The measurements at some selected places were verified by me and found satisfactory.

The work done is satisfactory

MANJUNATH. K
BOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Sketch for the Work of Construction of Culverts and Repairs, Reconstructions of Secondary Nala in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.



Junior Engineer
Ward No. 11

verified

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Construction of Culverts and Repairs, Reconstructions of Secondary Nala in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

hotos for the Work of Construction of Culverts and Repairs, Reconstructions of Secondary Nala in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos for the Work of Construction of Culverts and Repairs, Reconstructions of Secondary Nala in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT